

-1/17-




FIG. 1

2/17  
FIG. 2






FIG. 3

3/17  
FIG. 4



4/17  
FIG. 5A







FIG. 5B




5/17  
FIG. 6




6/17  
FIG. 7A



7/17  
FIG. 7B



8/17  
FIG. 8





9/17

FIG. 9A




FIG. 9B




FIG. 10





FIG. 11



10/17



FIG. 12A



FIG. 12B




FIG. 12C




FIG. 12D




FIG. 12E




FIG. 12F




FIG. 12G




FIG. 12H




FIG. 12I




FIG. 12J

11/17

FIG. 13A




FIG. 13B





FIG. 13C



12/17

FIG. 14A






FIG. 14B



VIEW DOES NOT SHOW SIDE PROFILE OF CAM BLADES

13/17  
FIG. 14C



14/17

FIG. 15A






FIG. 15B



VIEW DOES NOT SHOW SIDE PROFILE OF CAM BLADES

15/17

FIG. 15C



16/17

FIG. 16

